

Tuboscope | NOY Wellbore Technologies

CUSTOMER	MSF
REQD	IN HOUSE
LOCATION	MSF YARD

INCOMING	BLACLIGHT	N	ULTRASONIC		TRANSVERSE	N
OUTGOING	PENETRANT		VISUAL	N	LONG.	N

_____ OF _____ Reports

Comments = (DS = Damaged Shoulder, DT = Damaged Thread, CRK = Crack, SW = Swelled Box, RF = Field Reface, MRF = Machine Reface)

Inspectors: Brandon Bourque, Ray Zech level II
Date: 12/6/2022
Monitor: _____