



BHA DIMENSIONAL INSPECTION REPORT

1411 WEST ADIRAL DOYLE DRIVE
NEW IBERIA, LA 70560
337-367-9405

CUSTOMER: _____
ORDERED BY: _____
RIG: 0 _____
PO/AFE #: 7114 _____
WELL INFO: 0 _____
LEVEL II INSPEC.(s): B.MELANCON/T.COLE

DATE: 6/5/2024
WO NUMBER: 10155
DIM. REPORT#: 10155A
DT NUMBER: 10155
JOB SITE: NEW IBERIA, LA

Connection Repairs					
0	DT	Damaged Threads	0	PS	Pitted Seal
0	DSH	Damaged Shoulder	0	CRK	Cracked Connection
0	DS	Damaged Seal	0	MRF	Mach. Shop Reface
0	PT	Pitted Threads	0	REF	Reface by ESI
0	PSH	Pitted Shoulder			

COIL AMPS: _____
UV LAMP INT.: _____ $\mu\text{w}/\text{cm}^2$
BATH STRENGTH: _____ % 100 ml Tube

TYPE INSPECTION: DS-1 4th Edition Cat 3-5

Item #	Serial #	Description	Connection Size		O.D.	Pin I.D.	F.Neck / Tong Length	Bevel Dia.	Shld Width	Pin Length	Pin Cyl. Dia.	Ret. Grv.		Pin		Box C'Bore		Box Depth	Bore Back		Float Bore		Shd to Shd Length	Conn. Result	COMMENTS
												LGTH	DIA	LGTH	DIA	LGTH	DIA		LGTH	DIA	LGTH	DIA			
1	S355	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.65	OK	
			3 1/2 IF	BOX	4 3/4		1.70	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
2	S357	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.78	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
3	S356	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.60	OK	
			3 1/2 IF	BOX	4 3/4		1.78	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
4	S3516	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.80	OK	
			3 1/2 IF	BOX	4 3/4		1.88	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
5	S359	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.85	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
6	S3501	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.70	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
7	S3502	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
8	S3515	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.60	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.60	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				
9	S3511	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.65	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0	OK				

10	S3518	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.65	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
11	S3510	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.20	OK	
			3 1/2 IF	BOX	4 3/4		1.70	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
12	S3504	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.65	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
13	S3513	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.65	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
14	S3512	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.70	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.60	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
15	S3517	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.65	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
16	S3505	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.70	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	31.55	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	
17	S354	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.55	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0		OK	



ELLIOTT SERVICES, INC.

1411 WEST ADIRAL DOYLE DRIVE
NEW IBERIA, LA 70560
337-367-9405

BHA DIMENSIONAL INSPECTION REPORT

CUSTOMER:
ORDERED BY: _____
RIG: 0 _____
PO/AFE #: 7114 _____
WELL INFO: 0 _____
LEVEL II INSP.(s): B.MELANCON/T.COLE

DATE: 6/5/2024
WO NUMBER: 10155
DIM. REPORT#: **10155A**
DT NUMBER: **10155**
JOB SITE: _____ NEW IBERIA, LA

Connection Repairs

0	DT	Damaged Threads	0	PS	Pitted Seal
0	DSH	Damaged Shoulder	0	CRK	Cracked Connection
0	DS	Damaged Seal	0	MRF	Mach. Shop Reface
0	PT	Pitted Threads	0	RF	Reface by ESI
0	PSH	Pitted Shoulder			

COIL AMPS: _____
UV LAMP INT.: _____ $\mu\text{w}/\text{cm}^2$
BATH STRENGTH: _____ % 100 ml Tube

TYPE INSPECTION: DS-1 4th Edition Cat 3-5

Item #	Serial #	Description	Connection Size		O.D.	Pin	I.D.	F.Neck / Tong Length	Bevel Dia.	Shld Width	Pin Length	Pin Cyl. Dia.	Rel. Grv.		Box C'Bore		Box Depth	Bore Back		Float Bore		Shd to Shd Length	Conn. Result	COMMENTS
													LGTH	DIA	LGTH	DIA.		LGTH	DIA.	LGTH	DIA.			
1	S3503	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.65	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.55	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0			OK	
2	S3514	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.75	OK	
			3 1/2 IF	BOX	4 3/4		1.75	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0			OK	
3	S3506	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.70	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.80	OK	
			3 1/2 IF	BOX	4 3/4		1.85	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0			OK	
4	S3358	HWDP	3 1/2 IF	PIN	4 3/4	2 9/16	1.75	4 19/32	1/4	4	0	0	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	30.70	OK	
			3 1/2 IF	BOX	4 3/4		1.85	4 19/32	7/32	N/A	N/A	N/A	N/A	9/16	1/4	4 3/4	0	0	0	0			OK	

Scotty requested via email:

Please release 4 Jts of my 3-1/2 HW to Lance Guichard with Guichard Drilling. Please use PO # 7114 and that's the release # also.

Lacie please use that number on all paperwork including invoice.

Paul please take the inspection numbers off of the 4 jts you load so we can match up with the reports.